## MDTools 775 SP1 - Readme

Applicability: MDTools 775 with/without Hotfix 01/02/03 installed

Issues Resolved:

- 1. Inserting concentric undercuts on a SUN cavity displays an incorrect validation message.
- 2. Option to deactivate Automatic Update of Drawing not provided.
- 3. Using the Create Views command on an .iam (Assembly) file with the Display Center Mark option selected, throws an exception.
- 4. Edit Cavity allows duplicate Component IDs in the Virtual mode.
- 5. Shrink Wrap Assembly with engraving, throws an exception.
- 6. In a specific case, Component ID gets Cavity Name when using the Update Drawing command.
- 7. When a manifold has more than one angle hole, the Create Machining Drawing command throws an error.
- 8. Different-sized bolt holes assigned same bolt hole size by the Mirror Footprint command.
- 9. Editing a block after recreating balloons in a 2D drawing causes instablity.
- 10. Auto Assemble throws an exception when a CAD model assigned to an Orifice Plug is missing.
- 11. Update Assembly command crashes Inventor while updating an assembly file in an Italian region.
- 12. Location of the O-ring groove's machining callout does not get stored when using the Update Drawing command.
- 13. The Machining chart does not update values, per set precision for Angle holes.
- 14. When inserting a cavity from HyDraw Schematic, engravings get offset.
- 15. Angle holes created using the Copy Multiple command are assigned incorrect nets by the Assign Net command.
- 16. When a manifold has an engraving sketch instead of an engraving text, the Create Machining Drawing command throws an error.

Date: Nov 1, 2019

## MDTools 775 Hotfix 03 - Readme

Applicability: MDTools 775

Addressed an additional issue with Flexera licensing TLS 1.0 to TLS 1.2 upgrade.

Date: Oct 3, 2019

## MDTools 775 Hotfix 02 - Readme

Applicability: MDTools 775

Critical Security Update for Cloud License: Apply before Sep 10, 2019

MDTools to FlexNet Operations Cloud cryptographic protocol upgraded.

Transport Security Layer TLS 1.0 to TLS 1.2.

Date: Aug 27, 2019

## MDTools 775 Hotfix 01 - Readme

Applicability : MDTools 775

Issues Resolved:

1. When using the Create Machining Drawing command, some machining sequence rows may get deleted on breaking into multiple sheets. (Part Environment)

2 Update Drawing command causes instability.

Date: Aug 14, 2019