

## HyDraw CAD® 2021 Hotfix 10 EN

**Applicability:** HyDraw CAD 2021 EN with Service Pack 1 EN

### Issues Resolved:

1. Stability deterioration occurs when Microsoft references are not cleared using the HyDraw Property Manager.
2. Crashing occurs in specific cases of editing a symbol in Symbol Build Mode.
3. After running Export to MDTools, previews of symbols do not show.
4. B port on opposing sides of the Slip-In Valve symbol incorrectly assigned under different nets when creating a netlist.
5. Running Export to MDTools gives an unspecified error to specific drawings.
6. Running Export to MDTools causes an undefined net name for a 3-port slip-in cartridge valve.
7. In specific cases, renaming a net after creating the Net List gives an unspecified error.
8. Computer being idle results in a lack of the symbol preview when moving symbols.
9. Inconsistent behavior when running Export to MDTools with other names defined for a symbol's ports.

Date: April 1, 2022