

HyDraw® CAD 2022 Hotfix 01 IT

Applicability: HyDraw CAD 2022 IT

Issues Resolved:

1. The modified Parts List style, manually defined by the user, gets overridden and not used when opening HyDraw files.
2. When changing the Component Item ID, the Accessory Item ID does not reflect the changes.
3. Display formats are not displayed after adding an accessory through the ribbon or context menus.
4. Inconsistent units are displayed in the View Model Properties dialog compared to the symbol displayed in the drawing.
5. Item IDs are missing in new symbols created in Symbol Build Mode.
6. Hydraulic motor and bi-directional arrow hatch displayed as a circle in the dwg created using the Simplify DWG command.
7. An error within the Italian database resulted in no display of data type.
8. Hatch in some arrows changed to a circle in the dwg file created using the Simplify DWG command.
9. Incorrect translation for break line command.
10. Unable to access FluidPowerTools.com using the HyDraw Library Explorer.
11. When searching for symbols from FluidPowerTools.com within the HyDraw Library Explorer, the "All" option is displayed twice within the listed manufacturers.
12. Symbol preview for a newly created symbol is incorrect within the HyDraw Library Explorer.

Date: August 22, 2022