

MDTools® 785 Hotfix 02

Applicability: MDTools 785 with Service Pack 1

Fixed Service Pack 1 issues:

1. Align Cavities command updated the wrong dimensions.
2. Drill holes caused errors when inclined in the Feature mode.

Date: Nov 29, 2022