

## MDTools® 975 Hotfix 03

**Applicability:** MDTools 975 with Service Pack 01

**Issues Resolved:**

1. Advanced hole features fail in certain types of intersections with other features. If MDTools detects the hole feature has failed it will switch to using a revolved cut like previous versions of MDTools.

Date: Dec 8, 2021