

## HyDraw® CAD 2021 Service Pack 1 IT

Applicability: HyDraw CAD 2021 IT with/without Hotfix 9.0001 installed

## Issues Resolved:

- 1. HyDraw CAD performance enhanced
- 2. Explode command speed enhanced
- 3. Net List does not match in export to MDTools function with the Net List created using the Nets List command
- 4. Export to MDTools sometimes displaying incorrect net information
- 5. Unhandled exception error pops up for Nets List command.
- 6. Message when trying to borrow a network term license reworded for clarity.
- 7. Inconsistent row movement in 'Pipe & Tube' List Format in HyDraw Options.
- 8. Display Setting set to Hide not getting retained on changing the diameter of connection lines.
- 9. In Lists and Charts Format, when a property is added between 'From' and 'To', Move Up and Down buttons do not work.
- 10. Break in Connection Line displays although the line has no Line ID.
- 11. Adding a new display format causes a break in the connection lines due to the text appearing.
- 12. Search is taking the step back to the previous Search result when using FPT.com
- 13. Unable to change the zoom extent with Net List is opened.
- 14. In the default Connector List format, there is no space between Property Name 'Line ID' causing an error to appear.
- 15. In Build Mode, on unselecting 'Name' from Edit Symbol Port, on revisit, the Port name gets deleted.
- 16. Accessory Item IDs not incrementing properly
- 17. After changing the Component Item ID manually, the automatic numbering for accessory item IDs is incorrect
- 18. Port Names being scaled unnecessarily when using Scale and changing the text height.
- 19. Export to MDTools is displaying error message if setting library path is cancelled for the first time.
- 20. Symbol Port Name not matching with the Edit Symbol Port List creates an incorrect Net list.
- 21. Incorrect splitting of connection line when dropping symbol over it
- 22. Port selection not suggesting port size by the flow rate entered in the properties.



- 23. Add new folder button gets enabled if the symbol editor is opened and then a child library is selected from the library explorer.
- 24. Incorrect behavior of the library editor within child libraries
- 25. Line ID appearing for a connection line without anything to display.
- 26. Speed improvement for changing text height.
- 27. Speed improvement for Show Properties command.
- 28. Connection lines do not reconnect to a replaced external port.
- 29. Hitting undo removes jumpers in connection lines that existed before.
- 30. Hitting undo removes connection dots in connection lines that existed before.
- 31. Export to MDTools does not use correct displayed port names.
- 32. Warning message when starting a drawing with a HyDraw Title Block
- 33. HyDraw Title Blocks were incorrectly scaled
- 34. Insert component into drawing using "Part Number" present in the excel file
- 35. Headers carry into excel sheet when exported even though no headers option is selected
- 36. Accessory IDs are not getting updated when accessories are not displayed in drawing
- 37. Preview of connection lines is white with Auto Connect off
- 38. Port name changed upon running Export to MDTools twice
- 39. Incorrect Component Code displayed upon leaving blank in the Library Manager

Date: January 19, 2022

## HyDraw® CAD 2021 Hotfix 9.001

Applicability: HyDraw CAD 2021 EN-R/IT-R

## Issues Resolved:

- 1. With MS Access Database Engine 2016 installed, can Export Parts List and Other Lists to Excel.
- 2. In some cases when exporting Parts List to user defined template specified in HyDraw > Options throws error.
- 3. Boolean property value of a model property should get updated in HyDraw CAD as per the value in HLM.

Date: June 15, 2021

