

## HyDraw® CAD 2022 Hotfix 01 EN

Applicability: HyDraw CAD 2022

### Issues Resolved:

1. When changing the Component Item ID, the Accessory Item ID does not reflect the changes.
2. Display formats are not displayed after adding an accessory through the ribbon or context menus.
3. Inconsistent units are displayed in the View Model Properties dialog compared to the symbol displayed in the drawing.
4. Item IDs are missing in new symbols created in Symbol Build Mode.
5. Hydraulic motor and bi-directional arrow hatch displayed as a circle in the dwg created using the Simplify DWG command.
6. Hatch in some arrows changed to a circle in the dwg file created using the Simplify DWG command.
7. When editing a symbol, Add Display Format and Add Solenoid Info commands display incorrectly.
8. The modified Parts List style, manually defined by the user, gets overridden and not used when opening HyDraw files.

Date: August 9, 2022